

**2006 Bond Issue**  
**Completed Projects Identified and/or**  
**Funded from 2006 Bond Issue Proceeds**

<b>Identified</b>			<b>Percent</b>
<b>Year</b>	<b>Building</b>	<b>Description</b>	<b>Complete</b>
2006	Bluffsview	Carpet Replacement	100
2006	Bluffsview	Overlay Playground	100
2006	Bluffsview	Overlay Parking	100
2006	Bluffsview	Concrete Repairs	100
2006	Bluffsview	Window Replacement Room 32	100
2006	Bluffsview	Pump Insulation Repair	100
2006	Bluffsview	Repave site walk/bike paths	100
2006	Brookside	Overlay Parking	100
2006	Brookside	Overlay Playground	100
2006	Brookside	Boiler Replacement	100
2006	Brookside	ELS Room Heating Modifications	100
2006	Brookside	Classroom Lighting Replacement	100
2006	Brookside	Gymnasium Lighting Replacement	100
2006	Brookside	Interior Painting	100
2006	Brookside	Exterior Painting	100
2006	Brookside	Booster Pumps Replacement	100
2006	Brookside	Roof Wall Panel Replacement	100
2006	Brookside	replace carpet in the music room	100
2006	Colonial Hills	Suspended Ceiling System -Corridors	100
2006	Colonial Hills	Suspended Ceiling System -Classrooms	100
2006	Colonial Hills	Carpet Replacement-Pod Area	100
2006	Colonial Hills	Rear Door Replacement	100
2006	Colonial Hills	Domestic hot Water, Sinks in Pod Area	100
2006	Colonial Hills	Lighting Replacement -Classrooms	100
2006	Colonial Hills	Lighting Replacement -Corridors	100
2006	Colonial Hills	Overlay Playground	100
2006	Colonial Hills	Overlay Parking	100
2006	Colonial Hills	Concrete Repairs	100
2006	Colonial Hills	Boiler Replacement, Pod Area	100
2006	Colonial Hills	Exterior Painting	100
2006	Colonial Hills	Interior Painting	100
2006	Colonial Hills	Replace Gymnasium Lighting	100
2006	Education Center	Cooling Tower Replacement	100
2006	Education Center	Heat Pumps Replacement	100
2006	Education Center	Circulating Pumps Replacement	100
2006	Education Center	Replace UPS	100
2006	Education Center	Replace Leibert units in Computer Services Data Center	100
2006	Education Center	Expand electric in Computer Services Data Center	100
2006	Evening Street	Concrete Repairs-Front Entry and Stairs	100
2006	Evening Street	Chiller Sound Enclosure	100
2006	Evening Street	Overlay Playground	100
2006	Evening Street	Overlay Parking	100
2006	Evening Street	Boiler Replacement	100
2006	Evening Street	Exterior Painting	100
2006	Evening Street	Interior Painting-Cafeteria	100
2006	Evening Street	Roof Replacement	100

**2006 Bond Issue**  
**Completed Projects Identified and/or**  
**Funded from 2006 Bond Issue Proceeds**

<b>Identified</b>			<b>Percent</b>
<b>Year</b>	<b>Building</b>	<b>Description</b>	<b>Complete</b>
2006	Granby	Carpet Replacement	100
2006	Granby	Overlay Playground	100
2006	Granby	Heat Pump Loop Heat Shed	100
2006	Granby	Overlay Parking	100
2006	Granby	Resurface Restroom Epoxy Floor	100
2006	Granby	HVAC Pump System Replacement	100
2006	Granby	Valve and Gauge Replacement	100
2006	Kilbourne Middle	Paint Spray Booth	100
2006	Kilbourne Middle	Student Locker Replacement	100
2006	Kilbourne Middle	Concrete Replacement	100
2006	Kilbourne Middle	Overlay Parking	100
2006	Kilbourne Middle	South Rooftop Make-Up Air Unit Replacement	100
2006	Kilbourne Middle	Toilet Partition Replacement	100
2006	Kilbourne Middle	Carpet Replacement (5) Classrooms	100
2006	Kilbourne Middle	New paint in hallways	100
2006	Kingsmill	Overlay Staff and Bus Lots	100
2006	Kingsmill	South Fence Replacement	100
2006	Liberty	Carpet Replacement	100
2006	Liberty	Floor Tile Replacement Art/Gym/Cafeteria	100
2006	Liberty	Boiler Replacement	100
2006	Liberty	Electrical Switchgear Replacement	100
2006	Liberty	Overlay Parking	100
2006	Liberty	Interior Corridor Painting	100
2006	Liberty	Toilet Partition Replacement	100
2006	Liberty	Exterior Painting	100
2006	Liberty	Cafeteria Tables Replacement	100
2006	Liberty	Air Compressor Replacement	100
2006	Liberty	Lights need to be added in front of building	100
2006	Linworth Alternative	Building Carpet Replacement	100
2006	Linworth Alternative	Basement Drainage System	100
2006	Linworth Alternative	Multi-Purpose Room HVAC System Replacement	100
2006	Linworth Alternative	Classroom Unit Ventilators Valves Replacement	100
2006	Linworth Alternative	Overlay Parking	100
2006	Maintenance Facility	Overlay Parking	100
2006	Maintenance Facility	Replace Roof	100
2006	McCord Middle	Floor Tile Replacement	100
2006	McCord Middle	Overlay Playground	100
2006	McCord Middle	Structural Spray Track	100
2006	McCord Middle	Overlay Parking	100
2006	McCord Middle	Student Locker Replacement	100
2006	McCord Middle	Interior Painting	100
2006	McCord Middle	Resurface Restroom Epoxy Floors	100
2006	McCord Middle	HVAC Pumps System Replacement	100
2006	McCord Middle	Library Ductwork Modifications	100
2006	McCord Middle	Air Compressor Replacement	100
2006	McCord Middle	Unit Ventilator Repair	100

**2006 Bond Issue**  
**Completed Projects Identified and/or**  
**Funded from 2006 Bond Issue Proceeds**

<b>Identified</b>			<b>Percent</b>
<b>Year</b>	<b>Building</b>	<b>Description</b>	<b>Complete</b>
2006	McCord Middle	Locker Rooms HVAC Replacement	100
2006	McCord Middle	Replace boilers	100
2006	Perry Middle	Gymnasium Bleacher Replacement	100
2006	Perry Middle	Overlay Playground	100
2006	Perry Middle	Gymnasium Locker Replacement	100
2006	Perry Middle	Boiler Replacement	100
2006	Perry Middle	Boiler Room Piping Reconfiguration	100
2006	Perry Middle	Overlay Parking	100
2006	Perry Middle	Concrete Repairs -Sidewalks	100
2006	Perry Middle	Gymnasium HVAC Replacement /Relocation	100
2006	Perry Middle	Girls Toilet Partitions	100
2006	Perry Middle	Circulating Pump Replacement	100
2006	Perry Middle	Resurface Lockerroom Epoxy Floors	100
2006	Perry Middle	Floor Tile Replacement- Staff Restrooms	100
2006	Perry Middle	Entrance Door Replacement	100
2006	Slate Hill	Playground Lighting, Rear of Building	100
2006	Slate Hill	Site Lighting: Worthington Woods Area	100
2006	Slate Hill	Overlay Parking	100
2006	Slate Hill	Concrete Replacement	100
2006	Slate Hill	Window Replacement Room 32	100
2006	Slate Hill	Additional Gymnasium Lighting	100
2006	Slate Hill	Interior Painting	100
2006	Slate Hill	Stage Curtain Replacement	100
2006	Slate Hill	Replace Chiller	100
2006	Sutter Park	Additional Site Lighting West Playground	100
2006	Sutter Park	Overlay Playground	100
2006	Sutter Park	Chiller Replacement	100
2006	Sutter Park	Condenser Unit Replacement	100
2006	Sutter Park	Overlay Parking	100
2006	Sutter Park	Concrete Replacement	100
2006	Sutter Park	Boiler Replacement	100
2006	Sutter Park	Interior Painting	100
2006	Sutter Park	Resurface Restroom Epoxy Floors	100
2006	Thomas Worthington	Track Replacement	100
2006	Thomas Worthington	Concrete Replacement Entrance 4-Stairs and Walk	100
2006	Thomas Worthington	Site Lighting Replacement - West End	100
2006	Thomas Worthington	Foundation Leaks Room	100
2006	Thomas Worthington	Wrestling Room Exhaust Ventilation	100
2006	Thomas Worthington	Loading Dock Railing	100
2006	Thomas Worthington	East Wing Door Roof Overhangs	100
2006	Thomas Worthington	Dow Nelson Fieldhouse - Roof Replacement	100
2006	Thomas Worthington	Auditorium Roof	100
2006	Thomas Worthington	Tennis Court Surface Coating	100
2006	Thomas Worthington	Athletic Field Renovations	100
2006	Thomas Worthington	Dow Nelson Fieldhouse - Interior Painting	100
2006	Thomas Worthington	Exhaust Fan Above Teacher Center - Replacement	100

**2006 Bond Issue**  
**Completed Projects Identified and/or**  
**Funded from 2006 Bond Issue Proceeds**

<b>Identified</b>			<b>Percent</b>
<b>Year</b>	<b>Building</b>	<b>Description</b>	<b>Complete</b>
2006	Thomas Worthington	Unit Ventilator Relocation - 177	100
2006	Thomas Worthington	(3) Unit Ventilators Replacement - Art Wing	100
2006	Thomas Worthington	(3) Electric Heating Unit Ventilators Replacement - 185, 186	100
2006	Thomas Worthington	Chilled Water Piping Insulation Replacement on Roof	100
2006	Thomas Worthington	Carpet Replacement Room 138/139/161/250/246	100
2006	Thomas Worthington	Guidance Suite Roof and Flashing Replacement	100
2006	Thomas Worthington	Replace all classroom laser boards (blackboards)	100
2006	Wilson Hill	Office HVAC Replacement	100
2006	Wilson Hill	Library Lighting Replacement	100
2006	Wilson Hill	Corridor Lighting Replacement	100
2006	Wilson Hill	Boiler Replacement ,Typical of 3	100
2006	Wilson Hill	Cafeteria HVAC Replacement	100
2006	Wilson Hill	Overlay Parking	100
2006	Wilson Hill	Overlay Playground	100
2006	Wilson Hill	Concrete Replacement	100
2006	Wilson Hill	Toilet Partitions Replacement-East Wing	100
2006	Wilson Hill	Interior Painting	100
2006	Wilson Hill	Kitchen Grease Trap Installation	100
2006	Wilson Hill	Repave site walk/bike paths	100
2006	Worthington Estates	Building Carpet Replacement	100
2006	Worthington Estates	Additional Gymnasium Lighting	100
2006	Worthington Estates	Raypak Boiler Replacement	100
2006	Worthington Estates	Acoustic Ceiling Tile Replacement-Pod Area	100
2006	Worthington Estates	Courtyard Frame and Window Replacement	100
2006	Worthington Estates	Overlay Parking Lots	100
2006	Worthington Estates	Concrete Replacement	100
2006	Worthington Estates	Countertop Replacement-Art Room	100
2006	Worthington Estates	Interior Painting-Cafeteria	100
2006	Worthington Estates	Interior Painting-Classrooms and Corridors	100
2006	Worthington Estates	Concrete Replacement-Pod Area	100
2006	Worthington Hills	Gymnasium HVAC System	100
2006	Worthington Hills	(2) Hydropulse Boilers Replacement	100
2006	Worthington Hills	Roof Replacement	100
2006	Worthington Hills	Overlay Bike Path	100
2006	Worthington Hills	Overlay Patio Entry	100
2006	Worthington Hills	Overlay Parking	100
2006	Worthington Hills	Concrete Replacement	100
2006	Worthington Hills	Toilet Partitions-South Wing Restrooms	100
2006	Worthington Hills	Entrance Door & Glass Replacement	100
2006	Worthington Hills	Window Caulking	100
2006	Worthington Kilbourne	Carpet Replacement-Commons	100
2006	Worthington Kilbourne	Tennis Court Renovations	100
2006	Worthington Kilbourne	Carpet Replacement -Classrooms and Corridors	100
2006	Worthington Kilbourne	Track Replacement	100
2006	Worthington Kilbourne	Tennis Court Fencing Replacement	100
2006	Worthington Kilbourne	Erosion Control Dumpster Area	100

**2006 Bond Issue**  
**Completed Projects Identified and/or**  
**Funded from 2006 Bond Issue Proceeds**

<b>Identified</b>			<b>Percent</b>
<b>Year</b>	<b>Building</b>	<b>Description</b>	<b>Complete</b>
2006	Worthington Kilbourne	Standing Seam Roof Coating	100
2006	Worthington Kilbourne	Overlay Parking- Student Lot	100
2006	Worthington Kilbourne	Overlay Parking- Entrance Drives	100
2006	Worthington Kilbourne	Overlay Parking- Staff Lot	100
2006	Worthington Kilbourne	Entrance Paver Replacement	100
2006	Worthington Kilbourne	Cooling Towers Replacement	100
2006	Worthington Kilbourne	Overlay Parking-Loading Dock	100
2006	Worthington Kilbourne	Wood Shop Planer Station Lighting Upgrade	100
2006	Worthington Kilbourne	Painting (handrails & demountables)	100
2006	Worthington Kilbourne	Resurface Boiler Room Epoxy Floor	100
2006	Worthington Kilbourne	Sink Base and Cabinets Replacement -Art Room	100
2006	Worthington Kilbourne	AH17 Blower Assembly Replacement	100
2006	Worthington Kilbourne	AH1-AH18 Condensate Drain Plans Repair/Replacement	100
2006	Worthington Kilbourne	AH1-AH18 Damper Assemblies Repair/Replacement	100
2006	Worthington Kilbourne	AH1-AH18 Damper Motors Replace/Repair/Rebuild	100
2006	Worthington Kilbourne	Ductwork Dampers Replacement, as need throughout building	100
2006	Worthington Kilbourne	Air Compressor Upgrades	100
2006	Worthington Kilbourne	Dielectric Unions and Victaulic Fittings Replacement	100
2006	Worthington Kilbourne	AH1-AH18 Ductwork Repair	100
2006	Worthington Kilbourne	Expansion Tanks Sight Glasses Repair/Replacement	100
2006	Worthington Kilbourne	Heating/Cooling Control Valves Repair/Replacement	100
2006	Worthington Kilbourne	HVAC Strainers Replacement	100
2006	Worthington Kilbourne	HVAC Unit Insulation Repair/Replacement	100
2006	Worthington Kilbourne	Pumps & Air Handlers - Bearing Assemblies Repair/Replacement	100
2006	Worthington Kilbourne	Boiler Piping Modifications	100
2006	Worthington Kilbourne	Variable Speed Drives on HVAC Systems Replacements	100
2006	Worthington Kilbourne	Switchgear Contactors Repair	100
2006	Worthington Kilbourne	Interior Painting-Kitchen	100
2006	Worthington Kilbourne	Suspended Acoustic Ceiling Replacement- Kitchen	100
2006	Worthington Kilbourne	Add Reheat Coils in Room 109	100
2006	Worthington Kilbourne	Kitchen Hoods Repair	100
2006	Worthington Kilbourne	Stadium Fencing Replacement-East Side	100
2006	Worthington Kilbourne	Student Locker Replacement	100
2006	Worthington Kilbourne	Domestic Water Heaters Replacement	100
2006	Worthington Kilbourne	Entrance Heaters Replacement	100
2006	Worthington Kilbourne	Exhaust Fans Repair/Replacement	100
2006	Worthington Kilbourne	Door and moveable wall need repaired in Room 213/215	100
2006	Worthington Kilbourne	Door needs installed on men's restroom in 2nd fl. Teacher workro	100
2006	Worthington Kilbourne	Convert all chalkboards in building to whiteboards	100
2006	Worthington Park	Building Carpet Replacement	100
2006	Worthington Park	Heat Shed for 2-Pipe System	100
2006	Worthington Park	Additional Lighting- Gymnasium	100
2006	Worthington Park	Overlay Parking	100
2006	Worthington Park	Unit Ventilator System	100
2006	Worthington Park	Overlay Playground	100
2006	Worthington Park	Concrete Sidewalk Replacement	100

**2006 Bond Issue  
Completed Projects Identified and/or  
Funded from 2006 Bond Issue Proceeds**

<b>Identified</b>			<b>Percent</b>
<b>Year</b>	<b>Building</b>	<b>Description</b>	<b>Complete</b>
2006	Worthington Park	Interior Painting- Classrooms and Corridors	100
2006	Worthington Park	Resurface Restroom Epoxy Flooring	100
2006	Worthington Park	Boiler Isolation Valves Replacement	100
2006	Worthington Park	Air Compressor Replacement	100
2006	Worthingway Middle	Floor Replacement -Gymnasium	100
2006	Worthingway Middle	Folding Partition Replacement	100
2006	Worthingway Middle	Overlay Parking	100
2006	Worthingway Middle	Concrete Sidewalk Replacement	100
2006	Worthingway Middle	Gymnasium HVAC Renovations	100
2006	Worthingway Middle	Interior Painting-Classrooms and Corridors	100
2006	Worthingway Middle	Replace Gym Lockers	100
2006	Worthingway Middle	Replace carpet in library	100
2006	Worthingway Middle	Replace carpet in main office and adjacent offices	100